




RD250A/350A

MOTORCYCLE

M4-061

CARBURETOR MODIFICATION

The following modifications have been devised by the factory to improve the waterproof qualities of the carburetors and to prevent sticking slides.



PARTS ORDERING

NEW PART NO.	DESCRIPTION	PRICE	REMARKS
RD250A			
361-14101-02-00	CARBURETOR ASSY. (L)	\$36.10-A	New I.D. Mark
361-14102-02-00	CARBURETOR ASSY. (R)	36.10-A	36102
RD350A			
360-14101-02-00	CARBURETOR ASSY. (L)	36.10-A	New I.D. Mark
360-14102-02-00	CARBURETOR ASSY. (R)	36.10-A	36002
RD250A/350A			
361-14112-25-00	THROTTLE VALVE (L)	7.70-A	
361-14113-25-00	THROTTLE VALVE (R)	7.70-A	
401-14936-00-00	SEAT, spring	.48-A	
361-14946-00-00	PLATE, needle set	.94-A	Addition
97602-03120-00	PANHEAD SCREW	.16-A	Addition
92902-03100-00	WASHER, spring	.04-A	Addition
360-14158-00-33	TOP, mixing chamber	2.36-A	Addition
361-14147-00-00	O-RING	.36-A	Addition
360-26329-01-00	CAP, rubber	1.40-A	Addition

AFFECTED MACHINES

Factory installation begins with:

RD250A

E/N 206520

RD350A

E/N 213364

SALE OF PARTS

Carburetor assemblies are available now.

PLEASE BRING YOUR PARTS LIST UP-TO-DATE!

↑ ↑ ↑ ↑